



The American Energy Corporation

43521 Mayhugh Hill Road
Beallsville, OH 43716

Table Regarding 5H

Effluent Identification	Pond Number	5Hi Underground workings of Underground Mine	5Hii Coal Preparation Plant Areas and Coal Preparation Plant Assoc. Areas (excluding coal refuse piles)	5Hiii Active Mine Area with a pH Greater Than 6 Prior to Treatment	5Hiv Active Mine Area with a pH Less Than 6 Prior to Treatment	5Hv Wastewater from Coal Refuse Pile	5Hvi Controlled Surface Mine Drainage Wastewater	5Hvii Non-Controlled Surface Mine Drainage Wastewater	5Hviii Steep Slope and Mountaintop Removal Areas	5Hix Reclamation Areas	5Hx Pre-existing discharges that are within or hydrologically connected to a pollution abatement area.
OGM00142*BG outfall 001	Pond 001			X			X			X	
OGM00142*BG outfall 002	Pond 002			X			X			X	
OGM00142*GD outfall 018	Pond 018		X		X	X	X				
OIL00091*GD outfall 002	Pond 002	X		X			X				
OIL00091*GD outfall 008	Pond 008		X		X	X	X				
OIL00091*GD outfall 011	Pond 011	X		X			X				
OIL00091*GD outfall 012	Pond 012		X		X	X	X				
OIL00091*GD outfall 013	Pond 013				X	X	X				
OIL00091*GD outfall 014	Pond 014			X		X	X				
OIL00091*GD outfall 015	Pond 015				X	X	X			X	
OIL00091*GD outfall 017 Sewage Plant	Sewage Plant		X	X							
Pond 019	Pond 019						X				
Pond 1-S Pumped to Prep. Plant	Pond 1-S						X				
Pond 2-S	Pond 2-S						X				

Note: * All blank cells are not applicable.

CWA Section 308

I. Instructions

9. Documents and persons consulted examined or referenced

Referenced Documents

NPDES Permit OIL00091*GD

General NPDES: OHM000003 / OGM00142*BG

SMCRA Permit D-1159

SMCRA Permit D-0425

Application for NPDES Renewal can be found in 5D

Persons Consulted

Populated Original Response: Dennis Dubiel

Reviewer: Cody Mozena

Reviewer: Drew Hudson

Reviewer: Dave Washinsky

Reviewer: Crellin Scott

Environmental consultants contracted for preparation and submittal of the referenced documents.

Hamilton and Associates

2014-00657200778

AEC 16810